

<p align="center">TABSHEET BID # SDOC 08-B-139 KR PURCHASE, INSTALLATION AND REPAIR OF RADIO REPEATERS</p>	<p align="center">ASHTIN COMMUNICATION, INC. 4577 NW 6th Suite C Gainesville, FL 32609</p>	<p align="center">C.P.I. 3701 N. John Young Pkwy Ste. 101 Orlando, FL 32804</p>	<p align="center">Panther Electronics 1517 Kelly Ave. Kissimmee, FL 34744</p>	<p align="center">TERRYCOM 4155 Dow Rd., Unit #N Melbourne, FL 32934</p>
Completed Invitation To Bid cover page	YES	YES	YES	YES
Completed Bid submittal form	YES	YES	YES	YES
Drug Free Certification	YES	YES	YES	YES
Debarment Certification	YES	YES	YES	YES
Emergency/ Storm related catastrophe agreement from	YES	YES	YES	YES
Conflict of Interest form	YES	YES	YES	YES
References	YES	YES	YES	YES
Copy of Occupational License	YES	YES	YES	NO
Proof of Insurance	YES	YES	NO	NO
Hold Harmless Agreement	NO	NO	NO	NO
Copy of Bid submittal on CD?	YES	YES	NO	YES
Copy of manufacturer authorized ICOM dealer certificate	YES	YES	YES	YES
Addendum 1?	YES	YES	YES	YES
Addendum 2 and used revised price sheet?	YES	YES	YES	YES

TABSHEET BID # SDOC 08-B-139 KR PURCHASE, INSTALLATION AND REPAIR OF RADIO REPEATERS			ASHTIN COMMUNICATION, INC. 4577 NW 6th Suite C Gainesville, FL 32609		C.P.I. 3701 N. John Young Pkwy Ste. 101 Orlando, FL 32804		Panther Electronics 1517 Kelly Ave. Kissimmee, FL 34744		TERRYCOM 4155 Dow Rd., Unit #N Melbourne, FL 32934	
ITEM NO.	DESCRIPTION	QUANTITY EA.	UNIT	EXTENSION	UNIT	EXTENSION	UNIT	EXTENSION	UNIT	EXTENSION
1	<u>Total Turnkey Price for Radio Repeater</u> to include all materials, labor, miscellaneous charges for a complete installation in accordance with Section 1.03, and per Division 17 "Technology Standards and Specs". Total turnkey price shall include 100 linear feet of cabling. Please provide an Itemized breakdown of all materials and labor to be used on the project	4	\$ 3,124.00	\$ 12,496.00	\$ 3,120.00	\$ 12,480.00	\$ 4,450.00	\$ 17,800.00	\$ 3,380.00	\$ 13,520.00
2	Cost for additional cabling \$_____/linear feet		\$ 0.75		\$ 0.98		\$ 175.00		\$ 1.58	
3	Cost to upgrade to the FG4605 Antenna \$_____		\$ 49.00		\$ 155.00		\$ 345.00		\$ 36.00	
4	Cost to upgrade to the FG4607 Antenna \$_____		\$ 99.00		\$ 205.00		\$ 499.00		\$ 85.00	
5	Cost to reprogramming existing radios to match frequencies assigned by the FCC \$_____/per radio		\$ 7.50		\$ 5.00		\$ 15.00		INCLUDED	
6	Markup on parts and accessories _____%		20%		10%		30%		20%	
7	Hourly rate for repair work \$_____/per hour		\$ 45.00		\$ 75.00		\$ 85.00		\$ 60.00	
8	Are you a manufacturer authorized dealer for ICOM (If yes, submit a certificate)		YES		YES		YES		YES	
9	Best possible delivery/ installation completion time? _____days		20 DAYS		21 DAYS		45 DAYS		5 ARO	
10	Are you able to perform warranty work at your facility?		YES		YES		YES		YES	

TABSHEET BID # SDOC 08-B-139 KR PURCHASE, INSTALLATION AND REPAIR OF RADIO REPEATERS		ASHTIN COMMUNICATION, INC. 4577 NW 6th Suite C Gainesville, FL 32609	C.P.I. 3701 N. John Young Pkwy Ste. 101 Orlando, FL 32804	Panther Electronics 1517 Kelly Ave. Kissimmee, FL 34744	TERRYCOM 4155 Dow Rd., Unit #N Melbourne, FL 32934
11	List any exclusions to this bid: <hr/> <hr/> <hr/>			Motorola programming next day or 2 day freight	
		Overall Lowest Responsive, Responsible bidder			